

Oil Field Environmental Incident Summary

Incident: 20160416153408 **Date/Time of Notice:** 04/16/2016 15:34
Responsible Party: ENERPLUS RESOURCES USA CORPORATION
Well Operator: ENERPLUS RESOURCES USA CORPORATION
Well Name: SNOWY 147-94-13A-24H TF
Field Name: MCGREGORY BUTTES **Well File #:** 30865
Date Incident: 4/16/2016 **Time Incident:** 08:00 **Facility ID Number:**
County: DUNN **Twp:** 147 **Rng:** 94 **Sec:** 13 **Qtr:**
Location Description: Entire release remained contained on the well pad.

Submitted By: Tony Lucero **Received By:**

Contact Person: Chuck Antle
US BANK TOWER
950 17TH ST STE 2200
DENVER, CO 80202

General Land Use: Well/Facility Site **Affected Medium:** Well/Facility Soil

Distance Nearest Occupied Building: 2 Mile

Distance Nearest Water Well: 2 Mile

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Facility Site **Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
--	---------	-------	-----------	-------	----------	-------

Oil

Brine

Other	15	Barrels	15	Barrels
-------	----	---------	----	---------

Description of Other Released Contaminant:

Frac fluid

Inspected: **Written Report Received:** **Clean Up Concluded:**

Risk Evaluation:

None

Areal Extent:

The entire release remained confined to the well pad.

Potential Environmental Impacts:

The entire release remained confined to the well pad.

Action Taken or Planned:

Pumping operations were ceased; free-standing liquid was vacuumed up; remaining spill was absorbed and excavated. Recovered material will be disposed of at an approved offsite disposal facility. To prevent a recurrence of the incident, proper inspection and maintenance procedures will be followed.

Wastes Disposal Location: At an approved disposal facility.

Agencies Involved: BLM and Three Affiliated Tribes.

Updates

Date: 4/18/2016 **Status:** Reviewed - Assigned to Other Agency

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release was contained to the well pad. NDIC takes oversight.